



Ersatzteile / Spare parts

PDM600A1

Drechselmaschine
wood lathe

3902303976
0110

update: 22.01.2020

Skizze	Art.Nr.	Benennung	description
A 1	3902303001	Drehgriff	adjust knob
A 4-6,57,59	3902303002	Reitstockspitze kpl.	Tail spindel assy
A 8	3902303003	Abdeckung Reitstock vorn	front cover of tail
A 10	3902303004	Gehäuse Reitstock hinten	rear cover of tail
A 11,12,14	3902303005	Klemmhebel	Lever assy
A 16	3902303006	Profilkappe	base cover
A 17	3902303007	Grundprofil	base
A 20-27,18,62	3902303008	Werkzeugauflagenhalterung	Seat of tool carrie assy
A 28-30	3902303009	Werkzeugaufgabe	Tool carrier
A 31	3902303010	Drehgriff für Geschwindigkeitsregler	speed controlling knob
A 32	3902303011	Ein- / Ausschalter	switch
A 33	3902303012	Abdeckung Spindelstock vorn	front cover of nose
A 35	3902303013	Motorgehäuse links	motor housing left
A 36	3902303014	Motorgehäuse rechts	motor housing right
A 37	3902303015	Abdeckung Spindelstock hinten	rear cover of nose
A 40	3902303016	Rotor	rotor
A 41	3902303017	Stator	stator
A 44	3902303018	Kohlebürstensatz (=2 Stück)	carbon brush set (= 2 pcs.)
A 54	3902303019	Spindel	main shaft
A 56	3902303020	Planscheibe	disc chuck
A 57	3902303021	Mitnehmer	Head spindle
A 61	3902102025	Gabelschlüssel SW24	24 wrench
A 63	3902303022	Platine	PCB of regulating speed
A 64	3902303023	Gehäuse vorn	front cover -2
A 65	3902303024	Gehäuse hinten	rear cover -2
A 71	3906401015	Netzkabel EU-Stecker	cable and plug
A o.Abb.	7902300702	Stechbeitel Set	chisel kit