


Drechselmaschine


dmv 200

Ersatzteilliste


Spare parts list




- 1 = 7400 1100
- 2 = 7400 1200
- 3 = 7400 1400
- 4 = 7400 1500
- 5 = 7400 1509
- 6 = 0409 1263
- 7 = 0214 4006
- 8 = 7400 1008
- 9 = 0209 1235
- 10 = 0214 4004
- 11 = 7400 1304
- 12 = 7400 1006
- 13 = 0502 0301
- 14 = 0209 3147
- 15 = 0409 1262
- 16 = 7600 7003
- 17 = 7600 7004
- 18 = 7400 1013
- 19 = 7400 1012
- 20 = 0209 3363
- 21 = 0214 4005
- 22 = 0209 3405
- 23 = 7400 1015
- 24 = 7400 1700
- 25 = 0409 1262
- 26 = 0109 1109



- 1 = 7400 2000
- 2 = 7400 2150
- 3 = 7400 2043
- 4 = 0640 6206
- 5 = 7400 2005
- 6 = 0674 0101
- 7 = 0640 6305
- 8 = 0168 8548
- 9 = 7400 2050
- 10 = 0204 3912
- 11 = 7400 1600
- 12 = 0501 2802
- 12.1 = 0501 2807
- 13 = 7400 2018
- 14 = 7400 2019
- 15 = 7400 1006
- 16 = 0409 3361
- 17 = 0214 4006
- 18 = 0502 0301
- 19 = 0214 7626
- 21 = 0209 3345
- 25 = 0209 3346
- 26 = 0267 9806
- 27 = 0209 3404
- 28 = 7400 2700
- 29 = 7400 2616
- 30 = 0279 8143
- 32 = 7400 2800
- 33 = 0209 3405
- 34 = 0267 9808
- 35 = 7400 2017
- 36 = 0114 8141
- 37 = 7400 2632
- 38 = 0209 3365
- 39 = 7411 2950
- 40 = 7400 2929
- 41 = 7400 2924
- 42 = 7400 2031
- 50 = 7400 2020
- 51 = 0209 6327
- 52 = 7400 2021
- 53 = 7400 2022
- 54 = 7300 1025



- 1 = 7400 3100
- 2 = 7400 3200
- 3 = 7400 3109
- 4 = 7400 3110
- 5 = 0672 0101
- 6 = 0168 8801
- 7 = 0673 0101
- 8 = 7400 3900
- 9 = 0214 4006
- 10 = 0209 8602
- 11 = 7400 3700
- 12 = 7400 3122
- 13 = 0173 4370
- 14 = 6010 1109
- 15 = 0104 7119
- 16 = 0168 8801
- 17 = 7400 3119
- 18 = 6330 3226
- 19 = 7400 3111
- 20 = 7400 3121
- 21 = 0209 8647
- 22 = 6200 5117
- 23 = 7400 3112
- 24 = 7400 3113
- 25 = 0209 6443
- 26 = 0510 6100
- 27 = 7400 3114
- 28 = 7400 3115
- 29 = 7400 7600
- 30 = 0209 3347
- 31 = 0209 3404






- 1 = 7400 4000
- 2 = 7400 4800
- 3 = 7400 3606
- 4 = 7400 4817
- 5 = 7400 4100
- 6 = 7400 4700
- 7 = 0154 1737
- 10 = 0209 1234
- 11 = 7400 4300
- 12 = 7400 4511
- 13 = 7400 4006
- 14 = 0409 3184
- 15 = 0214 4007
- 16 = 7400 4007
- 17 = 7400 4015
- 18 = 0200 8436
- 19 = 7400 4600
- 20 = 0511 2100
- 21 = 7400 5100
- 22 = 7400 5200




- 1 = 7411 1400 230/50
- 1 = 7412 1400 400/50
- 2 = 7411 1401 230/50
- 2 = 7412 1401 400/50
- 3 = 7411 1300 230/50
- 3 = 7412 1300 400/50
- 4 = 0279 8128
- 5 = 7603 0080
- 6 = 0279 9151
- 7 = 7411 2350

- 7.1 = 7411 2352
- 7.2 = 0500 5402
- 8 = 0469 0001
- 9 = 7411 2360
- 10 = 0120 9306
- 11 = 0500 7701
- 12 = 0273 4905
- 13 = 0500 6252


- 14 = 7400 2051
- 14.1 = 7603 0111
- 15 = 6200 7022
- 16 = 0209 3367
- 16.1 = 0209 3366
- 17 = 0168 8548
- 18 = 7400 2052
- 19 = 0109 8813




- 1 = 7400 7500
- 2 = 7400 7501
- 3 = 0209 1429
- 4 = 0205 7118
- 5 = 0273 4904
- 6 = 7400 7200
- 7 = 7400 7102
- 8 = 0209 1331
- 9 = 7400 7203
- 10 = 0205 7138
- 11 = 0205 7139
- 12 = 7400 7100
- 13 = 7400 7101
- 14 = 7400 7103
- 15 = 7400 8600
- 16 = 7400 8601
- 17 = 7400 7300
- 18 = 7400 7301
- 19 = 7400 8700
- 20 = 7400 8701
- 21 = 7400 8800
- 22 = 7400 8801
- 23 = 7400 2028
- 24 = 0309 1105



1



2




7

- 1 = 7400 7400
- 2 = 7400 7401
- 3 = 7400 7402 Satz
- 4 = 7400 7403 Satz
- 5 = 7400 7404
- 6 = 7400 7700
- 7 = 6330 3624
- 8 = 0102 3801
- 9 = 6330 3625


2

- 10 = 7400 9000
- 11 = 7400 9001
- 12 = 7400 9002
- 13 = 0209 3367
- 14 = 0290 2108
- 15 = 7400 9003
- 15a = 7400 9004
- 15b = 7400 9005
- 16 = 0503 2101
- 17 = 0209 3350
- 18 = 0500 1203
- 19 = 0214 4004
- 20 = 0206 0333
- 21 = 0510 2100
- 22 = 0214 4005
- 23 = 0209 3167
- 24 = 0214 4007
- 25 = 7400 3114
- 26 = 7400 3115

3



4




3

- 27 = 7400 8100
- 28 = 7400 8200
- 29 = 0600 3206
- 30 = 7400 8106
- 31 = 0670 6206
- 32 = 0109 8806
- 32 = 0109 8805
- 33 = 0104 7252
- 34 = 7400 8107
- 35 = 6200 5117
- 36 = 0409 1289
- 37 = 0109 1111

4

- 1 = 7400 8900
- 2 = 7400 8906
- 3 = 7400 8904 1 Satz = 3 St.
- 4 = 7400 8905 1 Satz = 3 St.
- 5 = 7400 8907
- 6 = 0309 1249
- 7 = 0109 1429
- 8 = 7400 8903
- 9 = 0109 1107

5



5

- 1 = 7400 9100